



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

**export@sirsafety.com**  
**www.sirsafety.com**

Quality Management  
System Certificate  
UNI EN ISO 9001:2015

<b>Name: OVERCAP INFINITY BOOT</b>	<b>Code: MB2116Z9</b>	<b>MB21 FOOTWEAR OVERCAP SERIES</b>
------------------------------------	-----------------------	-------------------------------------

**Description**

Boot with grain leather upper, glass fibre toecap and composite midsole with 4 mm-constant thickness. Metal free.  
The PU/PU outsole, thanks to its particular design, guarantees a highly draining effect in the presence of liquids. The middle zone with grooves is designed to strengthen the grip on ladders. SRC grade anti-slip. The insole, made of high lift polyurethane foam, is particularly suitable for heavy footwear. Variable thickness: 4.5 mm in the front area and 9 mm in the heel area. With remarkable anti-shock and long lasting properties. Lined in the plant area. Antistatic.  
The lining uses materials with excellent cold insulation properties.


**Main features:**

- Heavy-duty design: suitable for rough terrain
- Increased wide fitting suitable for any kind of foot
- Wide-cellpolyurethane sole guarantees a high anti-shock effect
- The overcap protects the front leather from impact

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendment



<b>Category</b> <b>II</b>	<b>Colours</b> <b>BLACK</b>	<b>Available Sizes</b> <b>39 - 47</b>
------------------------------	--------------------------------	--

<b>Quantity/Carton</b>  <b>5</b>	<b>EC Standards</b> <b>EN ISO 20345</b>  Safety Class:S3 SRC	<b>Important Information</b> Construction, Agricultural sector and Forestry, Light and heavy mechanical industry, Metallurgic industry, Handling and Logistics, Cleaners, Maintenance technicians and Installers.  The footwear should be stored in a cool dry place, far from heat sources and direct light. Make sure footwear is in good condition, before use. If the shoes are damaged, replace them.  Clean the footwear with a soft brush and water.
<b>Dexterity</b>		