

Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686 VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com www.sirsafety.com





Name: RUSH jacket

Code: MC2514H1 MC25 CLOTHING - HARDWEAR SERIES

Description

Advanced multi-pocket work jacket made of 80% Polyester, 20% Cotton, Twill, weight 300 g/m . Solid, stain resistant, quick drying and water repellent.

- High-performance triple stitched seams, bar-tacked for increased
strength;

Ë ਸਿ^æَçˆ ૠ૾ૼ` ć ŸSSí ૠ૾ૼ^} dæþÁ^|-Ë&[ç^¦^åÁậ]^¦ૠ[•`¦^L ËÅy [Å@^^Ëåã]^}•ã] æþÆ@•o∱[&\^o ∱ã@Á\æ] ૠ}åÁX^|&\[í Êá}^Aá çœÆ@Æa ૠૠ[[àã^A∱@]}^Á]@ \^Á[&\^o\$ã@Á\æ] ﷺ ÅX^|&\[í ૠ]åÁ\^}Á@ other with detachable ID badge holder and hidden zippered vertical pocket;

ĔŹ√_[Á,˘~Á,[&\^o=Éá,}^Á]æ&áįč●Áş}^¦Á,[&\^oÆk[●^åÁ,ãc@źK^|&¦[íL

- Wear-and-tear reinforcements at the elbow;
- Elasticated inside cuffs, button-adjustable;

- Fleece-lined collar for maximum comfort;

- Adjustable waistband with side buttons;
- Reflex labels for extra visibility in low light conditions;

-3TíÁ^-/^&cą̄^Ádđjā;*Áæi[ǐ}ắÁ&@•dŹæč{•Áæ)åÁ;ç^¦Ác@Á@[ǎ/ŀ•Áq[Áa^Á highly visible when bending down;

ËĂŽ^•ć
c^åÁĮ ¦Á@æ{ ~ |Á`à•œa) &^•Áæ&&[¦åậ * ÁĮ ÁJ^\ [Ë/^¢í ÁĴœa) åæ}åÁ100;
- Industrial washable ISO 15797:2002.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471

Class 3*:

⁻Á0.80 m fluorescent material;

Á0.20 m retro-reflective material.

*If combined with the trousers Art. mc2511.

Category	Colours	Available Sizes
II	HI-VIS ORANGE	In stock: XS - L, 4X
Quantity/Carton	EC Standards	Important Information
	EN ISO 20471	General and Road Constructions, Road sign work,
	Class:3	Road and plants maintenance, Emergency response companies.
		The performance of the garment are guaranteed when it is correctly worn and fastened.
10		Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.
		We recommend to follow the washing instructions. Resistance up to 50 domestic washings.
Dexterity		Storage and cleaning
		$\boxtimes \boxtimes \boxtimes \bigcirc$

