



Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441

export@sirsafety.com www.sirsafety.com

Quality Management System Certificate UNI EN ISO 9001:2015

Name: HEAVY JACKET DENIM Code: MC2574Q8 MC25 CLOTHING - HARDWEAR SERIES

Description

Hardwearing multi-pocket work jacket made of Denim 85% Cotton, 15% Þ^|[} \frac{\mathbb{H}}{\mathbb{O}}\tilde{\mathbb{O}} \tilde{\mathbb{A}} \tilde{\mathbb{A than poly/cotton;.

Main features:

- -100% ÁÔ[¦åˇ¦æá Ál^āj-{¦&^{^}o•Á[¦Án¢&^]qā[}æþÁsˇ¦æààããcL
- High-performance triple stitched seams, bar-tacked to increase their strength;
- Ergofit, modern cut with preformed sleeves for a natural working position;
- ËÄV_[Ápad*^Ás@^^Ëåã[^}•ã[}adjÁs[^æ•oÁ,[&\^o•Á,ão@Ájad;Ásd;åÁx^]&l[íL - Two hidden vertical pockets with zipper, perfect for mobile phone and
- ËÁV¸[Án]æ&ãa,ĭ∙Áaãa^Án,[&\^o•ÁÔ[¦å ĭ¦æéÁ^ã,-{¦&^åÁ,ão@Áx^|&¦[íÁææàÊÃn,}^Á inner pocket;

ËÄÔ[¦åˇ¦æáÁ,^ædËæ)åËc^ædÁ^ā;-{¦&^{^}œ/ÁæcAó@^Án|à[ˌL ËÁK^|&¦[í Áscaåbŏ•ceaà,|^Á&v~⊸L

- Detachable ID-badge holder:

ËÁP^æçîÁsĭcîÁŸSSíÁ.ā[]^¦∙L

ËÂ/^• c^ åÂ[¦Á@e}{ ~ |Á à• cæ) &^• Áæ&&[¦åā] * Á[ÁJ^\ [Ë/^¢í ÁÛcæ) 忦åÁ100; - Industrial washable ISO 15797:2002.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.



Category	Colours	Available Sizes
I	BLUE	XS - 4X
Quantity/Carton	EC Standards	Important Information
	EN ISO 13688	Construction, Assembly processes, Installations, Logistics, Warehousing, Transport, Maintenance.
10		Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become awareof a damage, you should immediately replace it.
		We recommend to follow the washing instructions.
Dexterity		Storage and cleaning
		Data retrieval failed for the subreport,