



**SAFETY SYSTEM®**  
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciaci, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

export@sirsafety.com  
www.sirsafety.com



UNI EN ISO 9001:2015  
UNI EN ISO 14001:2015  
UNI EN ISO 45001:2018

<b>Name: MISTRAL short jacket</b>	<b>Code: MC3518H1</b>	<b>MC35 HIGH VISIBILITY CLOTHING - SUMMER</b>
-----------------------------------	-----------------------	---

**Description**

High visibility short jacket in Mistral fabric 55% cotton and 45% polyester, weight 245 g/m . It features a shirt collar, concealed closure with five buttons, two chest pockets with flap and Velcro, one of which is three-dimensional and equipped with a pen holder. High resistance jointed double seams. Double reflective bands around chest and on sleeves.

- The Mistral range guarantees excellent breathability thanks to the high percentage of cotton.
- Weight of 245 g/m , ideal for the summer.
- The fabric surface enhances the ability to repel liquid and dirt.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471

Class 2:  
= 0.50 m fluorescent material;  
= 0.13 m retro-reflective material.

The article is certified according to EN ISO 20471 class 3 when used in combination with the following products:  
MC3521, MC3522, MC3540, MC3543, MC3544, MC3612, MC3615

certified



<b>Category</b> II	<b>Colours</b> HI-VIS ORANGE	<b>Available Sizes</b> Made to order: 66 - 70 In stock: 44 - 64
-----------------------	---------------------------------	---

<b>Quantity/Carton</b> 20	<b>EC Standards</b> EN ISO 20471 Class:2	<b>Important Information</b> General and Road Construction, Road sign work, Road and plants maintenance, Emergency response companies.  The garment's performances are guaranteed when it is properly worn and fastened.  Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.  We recommend to follow the washing instructions. Resistance up to 50 washings.
------------------------------	--	---

<b>Dexterity</b>	<b>Storage and cleaning</b> 
------------------	---------------------------------