



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel. +39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

export@sirsafety.com  
www.sirsafety.com



UNI EN ISO 9001:2015  
UNI EN ISO 14001:2015  
UNI EN ISO 45001:2018

<b>Name: VELVET short jacket</b>	<b>Code: MC3616H1</b>	<b>MC36 HIGH VISIBILITY CLOTHING - WINTER</b>
----------------------------------	-----------------------	---

**Description**

High visibility short jacket made of Velvet fustian fabric 60% cotton and 40% polyester, weight 350 g/m . It features a shirt collar, concealed zipper closure with Velcro, two chest pockets with flap and Velcro, one of which is three-dimensional and equipped with a pen holder. High resistance jointed double seams. Double reflective bands on the bottom of the jacket and sleeves.

- The Velvetrage offers high visibility requirements and guarantees cold resistance and insulation.
- The compact fabric retains body heat and its surface enhances the ability to repel liquid and dirt.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471  
Class 2:  
= 0.50 m fluorescent material;  
= 0.13 m reflective material.

The article is certified according to EN ISO 20471 class 3 when used in combination with the following products:  
MC3521, MC3522, MC3540, MC3543, MC3544, MC3612, MC3615

certified



Category <b>II</b>	Colours <b>HI-VIS ORANGE</b>	Available Sizes Made to order: 66 - 70 In stock: 44 - 64
-----------------------	---------------------------------	--

Quantity/Carton          <b>20</b>	EC Standards <b>EN ISO 20471</b> Class:2	Important Information General and Road Construction, Road sign work, Road and plants maintenance, Service and assistance companies, Emergency response companies.  The performances of the garment are guaranteed when it is correctly worn and fastened.  Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.  We recommend to follow the washing instructions. Resistance up to 50 washings.
--	--	--

Dexterity

Storage and cleaning