



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciaci, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN ISO 45001:2018

Name: STARMAX jacket	Code: MC3914HD	MC39 HIGH VISIBILITY CLOTHING - WINTER KNITWEAR
-----------------------------	-----------------------	--

Description

High Visibility Softshell in 100% polyester 144 filaments TPU-laminated, bonded with 100% polyester 144 filaments microfleece, 335g/m Central zipper closure, bottom part of the jacket adjustable with drawstring and detachable hood with zipper and drawstring; detachable sleeves with zipper, cuffs adjustable with Velcro, two muff pockets with zipper closure and chest pocket with zipper. Heat-sealed segmented reflective band on shoulders, chest and sleeves.

Three different overlapping layers in Softshell fabric create a unique combination that guarantees high levels of comfort: the polyester microfleece inner layer makes the fabric soft and warm, the TPU membrane coupled with the polyester outer fabric allows moisture transpiration and thermoregulation, always keeping the body dry, and making the garment windproof and storm-proof.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471
Class 2:
= 0.50 m fluorescent material;
= 0.13 m reflective material.

certified



Category II	Colours HI-VIS ORANGE/BLUE	Available Sizes In stock: S - 4X
Quantity/Carton 10	EC Standards EN ISO 20471 Class:2	Important Information General and Road Construction, Road sign work, Road and plants maintenance, Transport, Logistics, Service and assistance companies, Emergency response companies. Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it. We recommend to follow the washing instructions.
Dexterity		Storage and cleaning