



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciaci, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN ISO 45001:2018

Name: SUPERTECH jacket	Code: MC5914ED	MC59 CLOTHING - SUPERTECH SERIES
-------------------------------	-----------------------	---

Description

Jacket in 75% cotton, 24% polyester, 1% antistatic fibre fabric, weight 280 g/m . It features a Chinese collar with Velcro, concealed front zipper closure with metal snap buttons, two chest pockets with flaps and Velcro; elastic cuffs, inner wallet pocket, reflective piping on chest and double reflective band on sleeves and waist.

THE JACKET SHALL BE WORN IN COMBINATION WITH THE TROUSERS.

- Supertech is flame retardant, antistatic, heat resistant, guarantees chemical protection and is high visibility.
- New protection from electric arc.
- Its multi-purpose features also ensure comfort and breathability.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425.

certified



Category III	Colours HI-VIS YELLOW/BLUE	Available Sizes Made to order: 40 - 40, 64 - 70 In stock: 44 - 62
----------------------------	--------------------------------------	--

Quantity/Carton 20	<p>EC Standards</p> <p>EN 1149-5 </p> <p>EN ISO 11611 Class:1 Values:A1</p> <p>EN ISO 11612 Limited Flame Spread:A1 Convective Heat:B1 Radiant Heat:C1 Molten Iron Splashes:E3 Contact Heat:F1</p> <p>EN ISO 20471 Class:3</p> <p>EN 13034 Type:6</p> <p>CEI EN 61482-2 APC:1 ATPV (Fabric):11 ELIM (Fabric):10</p>	<p>Important Information</p> <p>Petrochemical Industry, Metalworking industry, Refining Industry, Chemical Industry, Industrial Maintenance and Assemblies, Gas, Water and Electricity Mains Maintenance and Management, Oil & Gas industry.</p> <p>Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.</p> <p>We recommend to follow the washing instructions.</p>
----------------------------------	---	--

Dexterity	Storage and cleaning
------------------	-----------------------------

