



Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686 VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441 export@sirsafety.com www.sirsafety.com





Name: NEW METAL TOP METATARSO shoe Code: MB1530Z9 MB15 FOOTWEAR - NEW METAL TOP SERIES

## Description

Ankle high shoe with metatarsal protection, 200 joule composite toecap and Zero Penetration composite midsole. Full grain leather upper. PU FORCE dual density sole: High density polyurethane outsole with deep grooves offering excellent grip on uneven terrain.

Low density polyurethane insole, anti-weariness. Extra wide fitting shoe which provides a secure fit, whatever foot shape.

Anti-slipSRC standard.

DUAL FRESH Insoles in bi-component fabric with variable thickness and shock-absorbing properties. They are made fromspecial foams and particularly contact-friendly fabrics which prevent perspiration. 3D-TEX LINING for foot ventilation, reducing perspiration.

## Main features:

- High efficiency breathable lining
- Special protection with overcap
- Sharp-edged cleats to helpthe grip on wet floors
- Outsole with increased thickness
- Outsole with open angles deep grooves
- Outsole resistant to oils and hydrocarbons
- Anti-shock system
- Anti-slip ribbing
- Increased wide fitting suitable for any kind of foot

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments, and to conform to the requirements of European standards EN ISO 20345. It is classified as PPE Cat. II.



Category	Colours	Available Sizes
II	BLACK	In stock: 40, 47
Quantity/Carton	EC Standards EN ISO 20345  Safety Class:S3 M SRC	Important Information Construction, Agricultural sector and Forestry,
		Light and heavy mechanical industry, Metallurgic industry, Handling and Logistics, Cleaners, Maintenance technicians and Installers.
10		The footwear should be stored in a cool dry place, far from heat sources and direct light.  Make sure footwear is in good condition, before use. If the shoes are damaged, replace them.
		Clean the footwear witha soft brush and water.
Dexterity		Storage and cleaning