



Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686 VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441 export@sirsafety.com www.sirsafety.com





Name: ULTRALIGHT RED ARMOUR SHOE Code: MB2019BK MB20 FOOTWEAR - ULTRA LIGHT SERIES

Description

Ankle high shoe with Fast Lacing System and a cutting-edge seamless upper in Nylon. Fibreglass toecap and composite midsole with 4 mm-constant thickness.

SOLE: (EVA/RUBBER) Sole in highly expanded EVA material, with high anti-shock power, which makes the shoes more flexible and lighter. Outsole in nitrile rubber which assures perfect adhesion on either dry or wet surfaces.

INSOLE: Insole made in bicomponent material with shell in polyurethane foam and memory PU having variable thickness: 4 mm at the front and 9 mm in the heel area. Considerable anti-shock properties. Antistatic. DRY PLUS LINING: In polyester, with high draining power due to the high absorbing properties of the fabric and structure.

Main features:

- Extremely lightweight, breathable and comfortable
- Seamless upper for better fit to the foot, tear and abrasion resistance
- Fast Lacing system: quick wearing/release system
- High Durability Cap System: high durability TPU overcap system
- T-FLEX" composite midsole with constant thickness of 4 mm
- TPU rear supportto optimize stability in the heel area
- Ergonomic and ultra-flexible Eva/rubber outsole that guarantees a high level of comfort
- Suitable for environments characterized by soils with low degree of roughness

The product has been designed and manufactured tocomply with Regulation (EU) 2016/425 and subsequent amendments.



Category	Colours	Available Sizes
II	GREY/RED	36 - 43
Quantity/Carton	EC Standards	Important Information
	EN ISO 20345	Industrial plants
10	Safety Class:S3 SRC	The footwear should be stored in a cool dry place, far from heat sources and direct light. Make sure footwearis in good condition, before use. If the shoes are damaged, replace them. Clean the footwear with a soft brush and water.
Dexterity		Storage and cleaning