



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciari, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN ISO 45001:2018

Name: MISTRAL COLOR short jacket	Code: MC3519HD	MC35 HIGH VISIBILITY CLOTHING - SUMMER
---	-----------------------	---

Description

High visibility short jacket made of Mistral fabric 55% cotton and 45% polyester, weight 245 g/m with shirt collar, concealed five-button closure, two chest pockets with flap and Velcro, one of which tridimensional with pen holder, and double stitched seams for high resistance. Top part in high visibility fabric and bottom part, bottom of sleeves, collar and pocket flaps in non-fluorescent fabric. It features two loops of reflective bands around the sleeves and chest.

- The Mistral range guarantees excellent breathability thanks to the high percentage of cotton.
- Weight of 245 g/m , ideal for the summer.
- The fabric surface enhances the ability to repel liquid and dirt.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471
Class 2:
= 0.50 m fluorescent material;
= 0.13 m reflective material.

The article is certified according to EN ISO 20471 class 3 when used in combination with the following products:
MC3521, MC3522, MC3540, MC3543, MC3544, MC3612, MC3615

certified



Category II	Colours HI-VIS ORANGE/BLUE	Available Sizes Made to order: 66 - 70 In stock: 44 - 64
-----------------------	--------------------------------------	---

Quantity/Carton 20	EC Standards EN ISO 20471 Class:2	Important Information General and Road Construction, Road sign work, Road and plants maintenance, Emergency response companies. The performances of the garment are guaranteed when it is correctly worn and fastened. Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it. We recommend to follow the washing instructions. Resistance up to 50 washings.
------------------------------	--	---

Dexterity

Storage and cleaning