



Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441

export@sirsafety.com www.sirsafety.com





Code: MC3616H1 MC36 HIGH VISIBILITY CLOTHING - WINTER Name: VELVET short jacket

## Description

High visibility short jacket made of Velvet fustian fabric 60% cotton and 40% polyester, weight 350 g/m. It features a shirt collar, concealed zipper closure with Velcro, two chest pockets with flap and Velcro, one of which is three-dimensional and equipped witha pen holder. High resistance jointed double seams. Double reflective bands on the bottom of the jacket and sleeves.

- The Velvetrange offers high visibility requirements and guarantees cold resistance and insulation.
- The compact fabric retains body heat and its surface enhances the ability to repel liquid and dirt.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471

Class 2:

= 0.50 m fluorescent material;

= 0.13 m reflective material.

The article is certified according to EN ISO 20471 class 3 when used in combination with the following products:

MC3521, MC3522, MC3540, MC3543, MC3544, MC3612, MC3615

V@^Á, æā, Á^¢c^¦}ædÁæà¦æ3ÁarÁUÒSUËVÒÝí ÁÚæa)åædåÆT€€Á



OEKO TEX® certified Available Sizes Category Colours HI-VIS ORANGE Made to order: 66 - 70 Ш In stock: 44 - 64 Quantity/Carton **EC** Standards Important Information EN ISO 20471 General and Road Construction, Road sign work, Road and plants maintenance, Service and M Class:2 assistance companies, Emergency response companies. The performances of the garment are guaranteed

20

Dexterity

Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.

when it is correctly worn and fastened.

We recommend to follow the washing instructions. Resistance up to 50 washings.

Storage and cleaning

