



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciaci, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN ISO 45001:2018

Name: GLAMOUR long coat	Code: MC4013H1	MC40 HIGH VISIBILITY CLOTHING - RAINWEAR
--------------------------------	-----------------------	---

Description

High visibility coat in Wonderflex fabric, 100% PU coated polyester, 190 g/m . With concealed zipper closure with snap buttons, foldaway hood with elastic edge, waterproof pockets with buttons closure, elasticated windproof cuffs and reflective piping on shoulders.

- Glamour is completely waterproof and breathable.
- Incredibly elastic and flexible, it provides a high level of comfort and dynamism.
- Extremely resistant to wear-and-tear.
- Made in fabric with anti-acid properties, resistant to petrol and machine-washable.



The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO20471
Class 3:
= 0.80 m fluorescent material;
= 0.20 m reflective material.

certified



Category II	Colours HI-VIS ORANGE	Available Sizes In stock: S - 3X
------------------------------	--	--

Quantity/Carton 10	<p>EC Standards</p> <p>EN 343</p>  Water Resistance:3 Water Vapour Resistance:1	<p>Important Information</p> <p>Construction , Road Construction Works, Logistics, Transport, Forestry, Agriculture, Plants Maintenance, Gas, Water and Electricity Mains Maintenance and Management, Industrial plants installation and maintenance, Waste management companies.</p> <p>The performances of the garment are guaranteed when it is correctly worn and fastened.</p> <p>Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.</p> <p>We recommend to follow the washing instructions.</p>
	<p>EN ISO 20471</p>  Class:3	

Dexterity	Storage and cleaning
------------------	-----------------------------

