



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciaci, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

export@sirsafety.com  
www.sirsafety.com



UNI EN ISO 9001:2015  
UNI EN ISO 14001:2015  
UNI EN ISO 45001:2018

<b>Name: DRIVER jacket</b>	<b>Code: MC4114HC</b>	<b>MC41 HIGH VISIBILITY CLOTHING - WEATHER RESISTANT</b>
----------------------------	-----------------------	--

**Description**

Pilot jacket made of Oxford fabric 150D, lamination in water repellent PU; blue quilt in 80% polyester and 20% cotton, padding 180 g/m . Equipped with two-way front zipper closure, dirt-resistant collar edge in contrasting colour, two front pockets with snap button, vertical chest pocket with zipper, detachable sleeves with zipper, 100% polyester anti-pilling cuffs, inner pocket with Velcro fastening.

- The Driver series provides thermal protection and has been designed to ensure excellent breathability during use.


The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471  
Class 2:  
= 0.50 m fluorescent material;  
= 0.13 m reflective material.

certified



<b>Category</b> <b>II</b>	<b>Colours</b> <b>HI-VIS ORANGE/BLUE</b>	<b>Available Sizes</b> <b>In stock: S - 3X</b>
------------------------------	---	---

<b>Quantity/Carton</b>          <b>10</b>	<b>EC Standards</b> <b>EN ISO 20471</b>  <b>Class:2</b>	<b>Important Information</b> General and Road Construction, Road sign work, Road and plants maintenance, Transport, Logistics, Service and assistance companies, Emergency response companies.  Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.  We recommend to follow the washing instructions.
---	--	---

**Dexterity**

**Storage and cleaning**

