



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

export@sirsafety.com  
www.sirsafety.com



<b>Name: FLAME RETARDANT coverall</b>	<b>Code: MC5417R8</b>	<b>MC54 CLOTHING - FLAME RETARDANT SERIES</b>
---------------------------------------	-----------------------	---

**Description**

Coverall in 100% Flame Retardant cotton fabric, weight 315 g/m .  
Concealed metal zipper closure fastened with Velcro, elastic cuffs, side pockets and chest pocket with flaps and Velcro, elastic waistband, ankle zipper closures.

- It features remarkable multi-protective properties and is able to guarantee a high level of comfort while maintaining softness, lightness and breathability.
- It withstands up to 25 washes without altering the protective characteristics of the fabric.
- The full range can be produced in orange and red colours.



Suitable for protecting the operator from accidental contact with minor flames, molten metal splashes, low values of convective and radiant heat, and accidental electric contact up to 100 V of short duration.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425.

certified



<b>Category</b> <b>II</b>	<b>Colours</b> <b>EMERALD GREEN</b>	<b>Available Sizes</b> In stock: 44 - 62
------------------------------	--	---

<b>Quantity/Carton</b>          <b>10</b>	<p><b>EC Standards</b></p> <p><b>EN ISO 11611</b></p>  <p>Class:1 Values:A1</p> <p><b>EN ISO 11612</b></p>  <p>Limited Flame Spread:A1 Convective Heat:B1 Radiant Heat:C1 Molten Iron Splashes:E2 Contact Heat:F1</p>	<p><b>Important Information</b></p> <p>Metalworking Industry, Metallurgical Industry, Foundries, Plastic materials processing, Gas, water and electricity Industries, Firefighting Teams.</p> <p>Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.</p> <p>We recommend to follow the washing instructions. Resistance up to 25 washings.</p>
---	---	--

<b>Dexterity</b>	<b>Storage and cleaning</b>
------------------	-----------------------------

