



**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel. +39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

## TECHNICAL SHEET

[export@sirsafety.com](mailto:export@sirsafety.com)  
[www.sirsafety.com](http://www.sirsafety.com)



UNI EN ISO 9001:2015  
UNI EN ISO 14001:2015  
UNI EN ISO 45001:2018

**Name: POLYTECH STRETCH jacket**

**Code: MC5744QN**

**MC57 CLOTHING - POLYTECH SERIES**

### Description

Jacket in Twill 74% cotton, 22% polyester, 3% elastan, 1% conductive fibre, 280 g/m ; contrasting fabric in 75% cotton, 24% polyester, 1% conductive fibre, 280 g/m . It features a Chinese collar with Velcro for neck protection, concealed front zipper closure, three-dimensional chest pockets with flap in contrasting colour and Velcro, elasticated cuffs and reflective inserts on chest and elbows.

THE JACKET SHALL BE WORN IN COMBINATION WITH THE TROUSERS.

- The stretch fabric make it extra comfortable.
- The Polytech series is made with a multi-purpose fabric that combines antistatic properties with resistance to flames, heat and chemical products.
- Thanks to its features it is multi-purpose, practical and resistant, breathable and comfortable.

The product is designed and manufactured to comply with the requirements of Regulation (EU) 2016/425 and subsequent amendments.

certified



Category

III

Colours

BLUE/HI-VIS YELLOW

Available Sizes

Made to order: 38 - 38, 64 - 70  
In stock: 44 - 62

Quantity/Carton

20

EC Standards

EN ISO 11611



Class:1  
Values:A1+A2

EN ISO 11612



Limited Flame Spread:A1+A2  
Convective Heat:B1  
Radiant Heat:C1  
Molten Iron Splashes:E3  
Contact Heat:F1

EN 1149-5



EN 13034



Type:6

CEI EN 61482-2



APC:1  
ATPV (Fabric):11  
ELIM (Fabric):9

Important Information

Read the instructions carefully before use.  
Store in a cool, dry place, away from heat sources and away from light.

Before each use, carry out a visual check to ensure that the device is in perfect condition, undamaged and clean, and replace it if it is not intact.

Garments offer protection only for the part of the body actually covered and must therefore be integrated, depending on the intended use, with suitable PPE to protect exposed parts of the body (head, hands, feet).

Where necessary, use appropriate respiratory and eye protection.

The safety features indicated are only respected if the device is regularly worn and fastened and in perfect condition.

Follow the recommended washing instructions.

Dexterity

Storage and cleaning

